

End of Life Announcement (EOL)

Product Group: A-PLC
EOL-PLC-251219-2125-revA-SCA

Mitsubishi Electric Europé B.V
Factory Automation Scandinavia
 Hedvig Möllers gata 6, 223 55 Lund, Sweden

Date: 07.01.2026
 From: Strategic Product Marketing Team

<https://se.mitsubishielectric.com/fa>

Announcement of production discontinuation

Firstly thank you for the continuous support in selling our products. We have to announce discontinuation of MELSEC-L Series. The reason is difficulty in maintaining production system of some parts.

Materials to be discontinued		Replacement Materials (not necessarily 100% compatible)	
Material Description	Material	Material Description	Material
L26CPU-BT	238056	MXF100-8-N32	733089
L02CPU	238057	MXF100-8-N32	733089
L6DSPU	238058		
L6ADP-R2	238059	FX5-232ADP	280513
L6EC-ET	238062		
L61P	238063		
L63P	238064	MXF100-8-N32	733089
LX40C6	238085	FX5-16EX/ES	280505
LX41C4	238086	MXF100-X32	733093
LX42C4	238087	MXF100-X32	733093
LY10R2	238088	MXF100-Y16R	733094
LY41NT1P	238089	MXF100-Y32N	733095
LY42NT1P	238090	MXF100-Y32N	733095
L60AD4	238091	FX5-4AD	334430
LJ71C24	238093	FX5-232ADP	280513
LJ71C24-R2	238094	FX5-232ADP	280513
LD75D4	238095	RD75D4	279565
LD75P4	238096	FX5-16ET/ES-H	297442
LD62	238097	FX5-16ET/ES-H	297442
LD62D	238098	FX5-2HC/ES	702905
LJ61BT11	238099	FX5-CCL-MS	312299
LJ72GF15-T2	238100	RJ72GF15-T2	297947
LY40NT5P	242167	FX5-16EYT/ES	280503
LY40PT5P	242168	FX5-16EYT/ESS	280504
LY41PT1P	242169	MXF100-Y32P	733096
LY42PT1P	242170	MXF100-Y32P	733096
L26CPU-PBT	244977	MXF100-8-P32	733090
LJ71GF11-T2	246346	FX5-CCLGN-MS	504910
L60TCTT4	246347	FX5-4LC	312298
L60TCRT4	246348	FX5-4LC	312298
L60TCTT4BW	246349	FX5-4LC	312298

Material Description	Material	Material Description	Material
L60TCRT4BW	246350	FX5-4LC	312298
L6EXE	247226	R612B	279588
L6EXB	247227		
LC06E	247228	RC06B	279528
LC10E	247229	RC12B	279529
LC30E	247230	RC30B	279530
L6EC	249151		
LD75P1	251446	FX5-16ET/ES-H	297442
LD75P2	251447	FX5-16ET/ES-H	297442
LD75D1	251448	RD75D2	279564
LD75D2	251449	RD75D2	279564
LX10	255566	RX10	279546
L06CPU	263068	MXF100-8-N32	733089
L26CPU	263069	MXF100-8-N32	733089
LJ71E71-100	263072	FX5-ENET	409823
L26CPU-P	269669	MXF100-8-P32	733090
L06CPU-P	269670	MXF100-8-P32	733090
LH42C4NT1P	269671	MXF100-H32N	733097
LH42C4PT1P	269672	MXF100-H32P	733098
L60AD2DA2	269673	FX5-4AD	334430
LJ72MS15	271040		
L6ADP-R4	273657	FX5-485ADP	280514
L6TE-18S	277553		
L60ADIL8	279065	FX5-8AD	312297
L60ADVL8	279071	FX5-8AD	312297
L60MD4-G	279072	FX5-8AD	312297
LY18R2A	279074	FX5-8EYR/ES	280499
L60RD8	289962	FX5-8AD	312297
LJ51AW12AL	290898	NZ2AW1GNAL	600111
LD40PD01	296588	RD40PD01	307562
L60DAVL8	304494	FX5-4DA	325715
L60DAIL8	304545	FX5-4DA	325715

Phase Out Schedule

End of Life (EOL)	19.12.2025	<i>Date from which the discontinuation will become effective</i>
--------------------------	-------------------	--

Last Time Buy (LTB)	30.08.2027	<i>Date until when last Purchase Order from customer is accepted by Mitsubishi Electric</i>
----------------------------	-------------------	---

End of Service (EOS)	31.10.2034	<i>Date until support and service will be maximum available. If we are able, we are trying to repair a unit for a longer period. But this cannot be guaranteed</i>
-----------------------------	-------------------	--

Additional Information

The above listed material are just the main standard materials. Unfortunately, there is no replacement model.

Customer Action Requested

Mitsubishi Electric will accept customer orders for the above mentioned EOL materials through LTB. They cannot be cancelled. Orders after the LTB date will not be accepted. The order can be scheduled with different delivery dates after LTB.

If you have further questions, please contact your regional sales representative

A list of Mitsubishi Electric sales representatives is available at:

<https://emea.mitsubishielectric.com/fa/contact>