

EOL (End of Life) – Discontinuation of S-N600/800 contactors

Information about the discontinuation of S-N600/800 contactors.

Dear Sir or Madam,

After a very successful sales, Mitsubishi Electric has to announce the official change of production of the contactors S(D)-N600/800 due to the discontinuation of production of internal components There are direct successors, so please discuss possible replacement models with your contact person.

Materials to be discontinued		Replacement Materials	
Material Description	Material	Material Description	Material
S-N600 AC100V	113668	S-N600AB AC100V 2A2B	594983
S-N600 AC200V	113669	S-N600AB AC200V 2A2B	594984
S-N800 AC100V	113672	S-N800AB AC100V 2A2B	594985
S-N800 AC200V	113673	S-N800AB AC200V 2A2B	594986
S-N600 AC400V	113670	S-N600AB AC400V 2A2B	594987
S-N800UR AC200V	128842	S-N800ABUR AC200V 2A2B	594993
S-N800 AC400V	113674	S-N800AB AC400V 2A2B	594994
SD-N800 DC24V	246506	SD-N800AB DC24V 2A2B	594998
S-N600-COIL AC100V	125920	S-N600ABCOIL AC100V	594973
S-N600-COIL AC200V	125921	S-N600ABCOIL AC200V	594974
S-N600-COIL AC300V	125922	S-N600ABCOIL AC300V	594975
S-N600-COIL AC400V	125923	S-N600ABCOIL AC400V	594976
S-N600-COIL AC500V	125924	S-N600ABCOIL AC500V	594977
SD-N600-COIL DC24V	125966	SD-N600ABCOIL DC24V	594981
SD-N600-COIL DC48V	125967	SD-N600ABCOIL DC48V	594982
SD-N600 DC24V 2A2B	113688	SD-N600AB DC24V 2A2B	594989

End of Life (EOL)	30.04.2021	Date from which the discontinuation will become effective
Last Time Buy (LTB)	30.04.2021	Date until when last Purchase Order from customer is accepted by Mitsubishi Electric
End of Service (EOS)	30.04.2028	Date until support and service will be maximum available. If we are able, we are trying to repair a unit for a longer period. But this cannot be guaranteed.

Important information:

Mitsubishi Electric will accept orders for the above-mentioned EOL units until The date of the last order acceptance (LTB). Orders after this can no longer be processed.

General compatibilities and related options:

Please note that options, such as product variants, cables and interfaces can also be affected by the discontinuation. For more information, please contact your regional MITSUBISHI ELECTRIC Representative or Service.

Thank you for taking note of this EOL document. If you have any questions or if you have any concerns, please do not hesitate to contact your regional MITSUBISHI ELECTRIC representative or service.