

## EOL (End of Life) – Discontinuation

### Information about the discontinuation of QS90 Safety Relays

Dear Sir or Madam,

After a very successful sales, Mitsubishi Electric has to announce the official change of production of the QS90-Series Safety Relays. Parts of the above product are now obsolete, which is the reason why we have to discontinue this product. There are no direct successors. Please discuss possible replacement models with your contact person.

Materials to be discontinued		Replacement Materials	
Material Description	Material	Material Description	Material
QS90SR2SP-Q	215799		
QS90SR2SN-Q	215800		
QS90SR2SP-CC	215801		
QS90SR2SN-CC	215803		
QS90SR2SP-EX	215804		
QS90SR2SN-EX	215805		
QS90CBL-SE01	215806		
QS90CBL-SE15	215807		

<b>End of Life (EOL)</b>	31.07.2023	Date from which the discontinuation will become effective
<b>Last Time Buy (LTB)</b>	31.01.2025	Date until when last Purchase Order from customer is accepted by Mitsubishi Electric
<b>End of Service (EOS)</b>	31.03.2032	Date until support and service will be maximum available. If we are able, we are trying to repair a unit for a longer period. But this cannot be guaranteed.

#### Important information:

Mitsubishi Electric will accept orders for the above-mentioned EOL units until The date of the last order acceptance (LTB). Orders after this can no longer be processed.

#### General compatibilities and related options:

Please note that options, such as product variants, cables and interfaces can also be affected by the discontinuation. For more information, please contact your regional MITSUBISHI ELECTRIC Representative or Service.

Thank you for taking note of this EOL document. If you have any questions or if you have any concerns, please do not hesitate to contact your regional MITSUBISHI ELECTRIC representative or service.